




Trigger Inspection Report

This report summarises the monitoring required under Consent Condition SED.11(b) and relevant Project Management Plans.



Visual Inspection SED.111				
Area	Comments			
Mimi Stream	No concerns			
Mangapepeke Stream	No concerns			
SRP-1	No concerns			
SCY-SRP	Pond being pumped to, SRP not discharging			
SRP4600E	No concerns			
DEB4600E	DEB dry, not tested			

Manual Sampling: ESC Devices SED.11b (ii)							
Device Name	рН		NTU		Discharging?		
	Inlet	Outlet	Inlet	Outlet	Discharging:		
SRP-1	7.60	7.65	160	34.7	Yes		
SCY-SRP	7.72	7.75	166	108	No		
SRP4700E	7.67	7.95	91.3	51.5	Yes		

In-Stream Sampling (WQ1 - WQ5)

SED.11b (iii)

In-stream sampling will not be provided for this event, as stream levels have not receded since the previous rainfall trigger event (33.6mm, 30/10/2023).0





Sediment Deposition Monitoring

SFD.11b (iv)

Sediment deposition data is collected once it is safe to do so. All measurements are in mm.

Measured 05/10/2023		Stake top	Variation	Variation
	Baseline	to ground	from	from
	Dascillic	level	previous	baseline
			reading	(+ or -)
ST1(1)	906	935	-10	-29
ST1(2)	928	955	-20	-27
ST1(3)	923	911	-6	12
ST1(4)	926	910	-6	16
ST1(5)	900	935	-14	-35
ST1 (ave)	917	928	-11	-13
ST2(1)	1160	1160	-6	0
ST2(2)	1190	1190	-5	0
ST2(3)	1295	1283	-6	12
ST2(4)	1323	1300	5	23
ST2(5)	1290	1290	-5	0
ST2(ave)	1252	1245	-3	7
ST3(1)	1133	1131	1	2
ST3(2)	1090	1070	-13	20
ST3(3)	1131	1151	-1	-20
ST3(4)	1142	1132	-11	10
ST3(5)	1100	1115	-5	-15
ST3(6)	1222	1240	-1	-18
ST3(7)	1380	1381	0	-1
ST3(ave)	1171	1174	-4	-3
ST4(1)	1240	1231	1	9
ST4(2)	1272	1260	2	12
ST4(3)	1204	1190	1	14
ST4(4)	1342	1315	1	27
ST4(5)	1280	1222	-22	58
ST4(6)	1243	1202	0	41
ST4(ave)	1264	1237	-3	27
ST5(1)	965	950	-46	15
ST5(2)	979	930	-8	49
ST5(3)	1100	1082	-2	18
ST5(4)	1360	1363	8	-3
ST5(5)	1223	1175	-4	48
ST5(6)	1391	1381	-1	10
ST5(ave)	1170	1147	-9	23
(

Note: Baseline measurements were taken on 8/11/22

Data collected on 5/10/2023



