




## **Trigger Inspection Report**

This report summarises the monitoring required under Consent Condition SED.11(b) and relevant Project Management Plans.



Visual Inspection		SED.11b (i)
Area	Comments	
Mimi Stream	No concerns	
Mangapepeke Stream	No concerns	
SRP-1	No concerns, pond is discharging	
SRP-6D	No concerns, pond is discharging	
SCY-SRP	No concerns, pond is not discharging	
SRP4600E	No concerns, pond is discharging	
DEB-F14	No concerns, pond is not discharging	

Manual Sampling: ESC Devices SED.11b (						
Device Name	рН		NTU		Discharging?	
	Inlet	Outlet	Inlet	Outlet	Discharging	
SRP-1	7.75	7.65	10.1	11.67	Yes	
SRP-SCY	7.57	7.47	22.8	3.45	No	
SCY-6D	6.85	7.37	337	19.2	Yes	
SRP4700E	7.4	7.53	9.76	6.31	Yes	
DEB4660E	7.46	7.45	4.89	3.32	No	

## In-Stream Sampling

In-stream samples are not available for this event.





## Sediment Deposition Monitoring

Sediment deposition data is collected once it is safe to do so. All measurements are in mm. Data collected on 12/12/2023

Measured 12/12/2023	Baseline	Stake top to ground level	Variation from previous reading	Variation from baseline (+ or -)
ST1(1)	906	926	9	-20
ST1(2)	928	924	6	4
ST1(3)	923	993	-96	-70
ST1(4)	926	993	-75	-67
ST1(5)	900	913	-4	-13
ST1 (ave)	917	950	-32	-33
ST2(1)	1160	1146	9	14
ST2(2)	1190	1177	7	13
ST2(3)	1295	1258	-24	37
ST2(4)	1323	1300	7	23
ST2(5)	1290	1282	15	8
ST2(ave)	1252	1233	3	19
ST3(1)	1133	1124	8	9
ST3(2)	1090	1051	17	39
ST3(3)	1131	1142	23	-11
ST3(4)	1142	1119	6	23
ST3(5)	1100	1099	11	1
ST3(6)	1222	1225	-29	-3
ST3(7)	1380	1370	-62	10
ST3(ave)	1171	1161	-4	10
ST4(1)	1240	1229	8	11
ST4(2)	1272	1242	16	30
ST4(3)	1204	1179	7	25
ST4(4)	1342	1320	2	22
ST4(5)	1280	1199	77	81
ST4(6)	1243	1192	50	51
ST4(ave)	1264	1227	27	37
ST5(1)	965	944	15	21
ST5(2)	979	936	7	43
ST5(3)	1100	1061	0	39
ST5(4)	1360	1030	336	330
ST5(5)	1223	1160	27	63
ST5(6)	1391	1365	7	26
ST5(ave)	1170	1083	65	87

SED.11b (iv)