




Trigger Inspection Report

This report summarises the monitoring required under Consent Condition SED.11(b) and relevant Project Management Plans.



Visual Inspection		SED.11b (i)
Area	Comments	
Mimi Stream	Inspection undertaken, no issues to report.	
Mangapepeke Stream	No bulk earthworks occurring in this catchment.	
SCY-SRP	Inspection undertaken, no issues to report.	





Manual Sampling	: ESC Devic	es			SED.11b (ii)
Device Name	р	Н	N ⁻	TU	Discharging?
Device Name	Inlet	Outlet	Inlet	Outlet	Discharging:
SCY-SRP	8.23	7.66	424	127	Yes

In–Stream Sampling (WQ1 – WQ5)
In-stream samples are collected at the earl

SED.11b (iii)

In-stream samples are collected at the earliest convenience, once water levels recede and it is safe to do so. Samples are analysed at an accredited third-party laboratory.

Location	NTU	TSS (g/m3)	pН
WQ4 – Mimi Control (High)	16,500	30,000	6.5
WQ4 – Mimi Control (Low)	41,000	300,000*	6.3
WQ5 – Mimi Downstream (High)	4,200	12,000	6.6
WQ5 - Mimi Downstream (Low)	2,800	10,200	6.6
Comments			

Comments

*Analyst's Comment: Sandy sample.





Sediment Deposition Monitoring

SED.11b (iv)

Sediment deposition data is collected once it is safe to do so. All measurements are in mm. Data was collected on 16/11/2022.

	Baseline	Stake top to ground level	Variation from previous reading	Variation from baseline (+ or -)
ST1(1)	906	911	-6	-5
ST1(2)	928	933	-4	-5
ST1(3)	923	917	10	6
ST1(4)	926	921	0	5
ST1(5)	900	918	-10	-18
ST1 (ave)	917	920	-2	-3