

# Transport service licence

12-1 TSL



## Transport service licence

## 12-1 TSL

### Summary of legislation

#### Applicable legislation

- Land Transport Act 1998

#### Mandatory requirement

##### Business details

1. No certificate of fitness shall be issued in respect of any transport service vehicle unless the vehicle inspector has been notified of the transport service licence number under which the vehicle is being operated.

### Reasons for rejection

#### Mandatory requirement

1. The operator of a trailer that requires a transport service licence (**Table 12-1-1**) has not notified (**Note 2**) the vehicle inspector of the transport service licence number under which the trailer is operated.

**Table 12-1-1. Requirements for transport service licences**

Vehicles that require	Vehicles that do not require
<b>Goods service licence:</b>	
Heavy vehicles with a GVM of 6000 kg or more and capable of carrying goods	Vehicle recovery service vehicles Vehicles that operate solely in areas to which the public does not have right of access Vehicles used as places of abode that are not used in a rental service (eg motorhomes and dual-purpose motorhomes carrying horses where at least 50% of the floor space is constructed for human accommodation (this includes dedicated tractor and semi-trailer motorhomes)) Vehicles listed as farm vehicles (ie exempt class B licence) Mobile machines
<b>Vehicle recovery service licence:</b>	
Vehicle recovery service vehicles (ie designed or adapted for the purpose of towing or carrying motor vehicles for hire or reward)	Recovery vehicles of the New Zealand Defence Force
<b>Rental service licence:</b>	
Rental vehicles	

**Note 1** If correctly licensed, a vehicle requiring a transport service licence can be identified by the 'L' on the vehicle licence label.

**Note 2** For CoF purposes, the TSDA is expected to make a reasonable effort to request the TSL number from the driver. The TSL number must be entered into the system when the inspection is recorded, but where a TSL number cannot be obtained, fault code VLP must be entered.

