

Operator name	date	result	Action	Fault description
Cityline (NZ) Ltd	29-Jan-13	Fail	Green	Engine oil leak.
Cityline (NZ) Ltd	29-Jan-13	Fail	Green	Engine oil leak (sump plug).
Cityline (NZ) Ltd	29-Jan-13	Fail	Green	Seat not securely fitted. Right rear tag axle tyre insufficient tread.
Cityline (NZ) Ltd	29-Jan-13	Fail	Green	Engine oil leak. Left rear lower brake light to operate.
Cityline (NZ) Ltd	29-Jan-13	Fail	Green	Right rear tag axle tyre insufficient tread.
Cityline (NZ) Ltd	29-Jan-13	Fail	Green 2	Hand rail faulty. Luggage support rail faulty (front right).
Cityline (NZ) Ltd	29-Jan-13	Fail	Green 2	L/h screen washer to operate.
Cityline (NZ) Ltd	29-Jan-13	Fail	Green 2	Seats not securely fitted.
Cityline (NZ) Ltd	29-Jan-13	Fail	Green 2	Emergency exit instructions not affixed (roof hatch). Seat not securely fitted (rear). Note: Exhaust fumes entering bus.
Cityline (NZ) Ltd	29-Jan-13	Fail	Green 2	Insufficient emergency exits. Rear top left light mounting damaged.
Cityline (NZ) Ltd	29-Jan-13	Fail	Green 2	Emergency exit instructions not affixed.
Cityline (NZ) Ltd	29-Jan-13	Fail	Green 2	Hand rail faulty (left rear).
Cityline (NZ) Ltd	29-Jan-13	Pass	No Action	
Cityline (NZ) Ltd	29-Jan-13	Pass	No Action	
Cityline (NZ) Ltd	29-Jan-13	Pass	No Action	
Cityline (NZ) Ltd	29-Jan-13	Pass	No Action	
Cityline (NZ) Ltd	29-Jan-13	Pass	No Action	Note: Hubo mounted off centre.
Cityline (NZ) Ltd	29-Jan-13	Pass	No Action	
Cityline (NZ) Ltd	29-Jan-13	Pass	No Action	
Cityline (NZ) Ltd	29-Jan-13	Pass	No Action	
Wellington City Transport Ltd	19-Mar-13	Fail	Green 2	Notes only: L/h number plate light to operate. 4th seat r/h inner, last row r/h inner seat mounts to secure. L/h rear grab pole loose.
Wellington City Transport Ltd	19-Mar-13	Fail	Green 2	Rust between front axle/suspension mounts. L/h rear grab pole loose. Courtesy glass l/h rear loose. L/r inner seat mounting loose.
Wellington City Transport Ltd	19-Mar-13	Fail	Q Green	Washer to operate. Centre left courtesy glass loose. Exterior graphics to be cut/separated on emergency exit.
Wellington City Transport Ltd	19-Mar-13	Fail	Q Pink	3 x support poles loose/bolts missing. Rear window emergency exit signage too small & advertising signage to be cut on pull tag/beading.
Wellington City Transport Ltd	19-Mar-13	Fail	Q Pink	L/r park lights, number plate light, f/r park light to operate. Row 8 r/h seat bracket broken. L/h 2nd grab pole to secure.
Wellington City Transport Ltd	16-Apr-13	Fail	Green 2	Windscreen washer to operate.
Wellington City Transport Ltd	16-Apr-13	Fail	Green 2	Rear exterior Emergency Exit signage 63mm rather than 75mm. Corrosion on r/h headlight reflector.
Wellington City Transport Ltd	16-Apr-13	Fail	Green 2	2 x support poles loose. 1st row r/h seat bracket broken. Rear Tag Off bracket loose. Corrosion on l/h headlight reflector.
Wellington City Transport Ltd	16-Apr-13	Fail	Green 2	R/h last seat inner not securely fitted.
Wellington City Transport Ltd	16-Apr-13	Fail	Pink	Engine oil leak.
Wellington City Transport Ltd	16-Apr-13	Fail	Pink	Engine oil leak. 2 x support poles loose. Interior - Anti graffiti film on interior Emergency Exit to be trimmed. Emergency Exit hammer
Wellington City Transport Ltd	16-Apr-13	Fail	Pink	Diesel fuel leak. Rear seat to be secured. Rear courtesy glass to be secured.
Wellington City Transport Ltd	16-Apr-13	Fail	Pink	Engine oil leak. 2nd r/h support pole loose. Windscreen washer to operate.
Wellington City Transport Ltd	16-Apr-13	Fail	Q Pink	L/h front park light to operate. Front & rear l & r brake stroke in excess of manufacturers standard. Under Tow sign cannot be mounted on stone guard. Ringfeder locking pin missing.
Wellington City Transport Ltd	16-Apr-13	Pass	No Action	Note: Interior - Anti graffiti film on interior Emergency Exit to be trimmed.
Wellington City Transport Ltd	16-Apr-13	Pass	No Action	Note: Corrosion on l/h headlight reflector.
Wellington City Transport Ltd	16-Apr-13	Pass	No Action	
Wellington City Transport Ltd	16-Apr-13	Pass	No Action	Note: Interior - Anti graffiti film on interior Emergency Exit to be trimmed.
Wellington City Transport Ltd	16-Apr-13	Pass	No Action	
Wellington City Transport Ltd	16-Apr-13	Pass	No Action	Notes: Rear number plate unreadable. Rear School Bus sign dirty / paint overspray.
Wellington City Transport Ltd	16-Apr-13	Pass	No Action	Note: Interior - Anti graffiti film on interior Emergency Exit to be trimmed.
Wellington City Transport Ltd	16-Apr-13	Pass	No Action	Note: Interior - Anti graffiti film on interior Emergency Exit to be trimmed.
Wellington City Transport Ltd	17-Apr-13	Fail	Green 2	Rear Emergency Exit pull rings insufficient. Rear exterior Emergency Exit signage 63mm rather than 75mm. School Bus signage covers
Wellington City Transport Ltd	17-Apr-13	Fail	Pink	Checked 16 Apr 2013. Repeat inspection. Previous faults yet to be actioned. Additional fault - engine oil leak.
Wellington City Transport Ltd	17-Apr-13	Fail	Pink	Engine oil leak. Rear seats 3, 4, 5 loose. Rear Emergency Exit signage unreadable - repaired on site. Exhaust fumes entering bus.
Wellington City Transport Ltd	17-Apr-13	Fail	Q Green	L/h headlight reflector corrosion. 2 x support poles loose. Tag Off bracket loose. Faults repaired on site.
Wellington City Transport Ltd	17-Apr-13	Fail	Q Green	Emergency Exit r/h front has been changed to r/h 3rd window. Original signage to be removed. 2nd r/h support pole loose. Interior rear
Wellington City Transport Ltd	17-Apr-13	Fail	Q Green	R/h 7th seat loose. Inspected on site - movement in floor.
Wellington City Transport Ltd	17-Apr-13	Fail	Q Pink	Rear Emergency Exit pull rings insufficient - repaired on site. Notes: Minor engine oil leak. Rear seat 2nd left loose.
Wellington City Transport Ltd	17-Apr-13	Pass	No Action	
Wellington City Transport Ltd	17-Apr-13	Pass	No Action	
Wellington City Transport Ltd	17-Apr-13	Pass	No Action	
Wellington City Transport Ltd	17-Apr-13	Pass	No Action	Notes: L/h windscreen washer to operate. R/h 3rd support pole loose.
Wellington City Transport Ltd	17-Apr-13	Pass	No Action	Checked 16 Apr 2013. Repeat inspection. Previous fault yet to be actioned. Note: Corrosion on l/h headlight reflector.
Cityline (NZ) Ltd	24-Apr-13	Fail	Green 2	R/h cab marker light to operate. Windscreen damage (wiper scratches) left hand side. Notes: 4th row inner seat insecure. Front disc rotors to be checked for wear.

Operator name	date	result	Action	Fault description
Cityline (NZ) Ltd	24-Apr-13	Fail	Q Pink	Windscreen washers to operate. Rear seat insecure. Corrosion on headlight reflectors. 4th r/h support pole loose. Hubo obscured - cannot be read. Front left courtesy glass too close to support pole. Rear left courtesy glass insecure. 1st & 3rd axle brake rotors at or below manufacturers minimum specifications (36mm & 37mm).
Cityline (NZ) Ltd	24-Apr-13	Fail	Q Pink	Exhaust fumes entering bus. Multiple (x9) seats loose. L/h Emergency Exit signage on incorrect window. Rear l/h support pole upper
Cityline (NZ) Ltd	24-Apr-13	Fail	Q Pink	R/h headlight reflector corrosion. Windscreen washers to operate. R/h wiper blade damaged. R/h grab rail (between seats 2/3) insecure.
Cityline (NZ) Ltd	24-Apr-13	Fail	Q Pink	R/h 2nd & 5th row seat bases detached. Driver's seat to be secured. R/h rear Emergency Exit door width too small (390mm) - suggest
Cityline (NZ) Ltd	24-Apr-13	Fail	Q Pink	R/h cab marker light to operate. R/h headlight reflector corrosion. R/h headlight high beam to operate. Exhaust fumes entering bus.
Cityline (NZ) Ltd	24-Apr-13	Pass	No Action	
North City Bus Ltd	24-Apr-13	Fail	Green	Oil leak (rear of sump). L/h 9th & 10th row seats insecure. 2nd axle 39% brake imbalance.
North City Bus Ltd	24-Apr-13	Fail	Green	Cab marker lights to operate. Windscreen washers to operate. 2 x oil leaks (minor) - bell housing & oil filter. Note: Check & adjust rear brakes.
North City Bus Ltd	24-Apr-13	Fail	Q Pink	Multiple (x4) seats loose or detached. Exhaust fumes entering bus (holes under rear seat). 3rd axle brakes do not meet requirements - will
Wellington City Transport Ltd	6-May-13	Fail	Green 2	R/h 7 seat loose on outer mount. Notes: Grab rail between r/h seats 2 & 3 loose. Rear emergency exit has 2 piece filler strip - only
Wellington City Transport Ltd	6-May-13	Fail	Pink	Exhaust fumes entering bus. R/h 7, 9, rear 2 seats loose. L/h rear 1, 2 seats broken frame. Rear School bus sign to comply.
Wellington City Transport Ltd	6-May-13	Fail	Pink	Exhaust fumes entering bus. School bus signs to comply (front & rear).
Wellington City Transport Ltd	6-May-13	Fail	Pink	Rear emergency exit (exterior) pull ring missing. School bus signs to comply (front & rear). Note: Minor engine oil leak.
Wellington City Transport Ltd	6-May-13	Fail	Q Pink	Rear emergency exit single pull ring for 2 piece filler strip (interior & exterior). Note: Minor timing cover oil leak.
Wellington City Transport Ltd	6-May-13	Pass	No Action	
Wellington City Transport Ltd	7-May-13	Fail	Green 2	R/h rear seats 1 & 2 loose. Exterior rear emergency exit pull ring missing - repaired on site.
Wellington City Transport Ltd	7-May-13	Fail	Green 2	Exterior roof hatch emergency exit sign missing. Repaired on site.
Wellington City Transport Ltd	7-May-13	Fail	Pink	Exhaust fumes entering bus. Rear seat (centre) loose - repaired on site. Note: School bus signs to comply.
Wellington City Transport Ltd	7-May-13	Fail	Pink	Exhaust fumes entering bus. Engine oil leak. Right rear indicator to operate. R/h 3 seat loose. Note: Check roof hatch exterior signage.
Wellington City Transport Ltd	7-May-13	Fail	Pink	Exhaust fumes entering bus. L/h 8 seat broken frame.
Wellington City Transport Ltd	7-May-13	Fail	Pink	Exhaust fumes entering bus. Oil leak - hydraulic fan. L/h cab marker light to operate. L/h 8 seat loose. L/h interior front mirror cracked.
Wellington City Transport Ltd	7-May-13	Fail	Pink	Exhaust fumes entering bus. 2 x oil leaks - hydraulic fan, oil filter housing. L/h 4 inner seat loose. R/h seats 6, 9 brackets broken. School
Wellington City Transport Ltd	7-May-13	Fail	Pink	Exhaust fumes entering bus. Front School bus sign to comply. Engine oil leak (minor).
Wellington City Transport Ltd	7-May-13	Fail	Pink	Exhaust fumes entering bus. School bus signs to comply. Rear reflectors too small. R/h 9 seat loose. R/h headlight reflector discolouration.
Wellington City Transport Ltd	7-May-13	Fail	Pink	Exhaust fumes entering bus. Rear floor hatch panel insecure (possible exhaust fume entry point). R/h 7 seat loose.
Wellington City Transport Ltd	7-May-13	Fail	Pink	Engine oil leak. Front School bus sign to comply. R/h headlight reflector corrosion. Rear floor hatch panels insecure. Note: Check to establish
Wellington City Transport Ltd	7-May-13	Fail	Pink	Exhaust fumes entering bus. Severe oil leak.
Wellington City Transport Ltd	7-May-13	Fail	Q Pink	Exhaust fumes entering bus. Repaired on site.
Wellington City Transport Ltd	7-May-13	Pass	No Action	Note: School bus signs to comply.
Wellington City Transport Ltd	7-May-13	Pass	No Action	Not inspected but noted: Oil leak.
Wellington City Transport Ltd	7-May-13	Pass	No Action	Not inspected but noted: Oil leak.
Cityline (NZ) Ltd	9-May-13	Fail	Green 2	Right rear grab pole floor mount loose. L/h 5 outer seat loose. Rear seat R2 loose - repaired on site. Film to be trimmed to 10 mm from
Cityline (NZ) Ltd	9-May-13	Fail	Green 2	2nd axle inner tyre insufficient tread. Seats 1R, 8R, 2L, 3L, 4L, 5L, 10L & rear centre loose. Left rear grab rail & bottom mount loose.
Cityline (NZ) Ltd	9-May-13	Fail	Green 2	Rear reflectors to be compliant. Rear panel (engine compartment) damage - possible exhaust fume entry point. Rear door exit floor
Cityline (NZ) Ltd	9-May-13	Fail	Q Pink	R/h 7 seat back loose. R/h overhead grab rail loose. Luggage rails loose. Courtesy glass (lower - behind driver's seat) to be retained in
Cityline (NZ) Ltd	9-May-13	Fail	Q Pink	L/h 4 outer seat loose. Rear floor panel loose (screws missing) allowing entry of exhaust fumes. Minor oil leak. Notes: Lower rear panel
Cityline (NZ) Ltd	9-May-13	Fail	Q Pink	R/h luggage mounts / grab rails loose. Rear floor panel loose allowing entry of exhaust fumes. Anti graffiti film to be trimmed to 10 mm
Cityline (NZ) Ltd	9-May-13	Pass	No Action	Not inspected but noted: Oil sump wet - minor oil leak. Check rear floor area for possible exhaust leaks.
Wellington City Transport Ltd	9-May-13	Fail	Green	R/h 1 aisle seat loose. Wheel chair ramp floor covering damaged. L/h rear reflector broken. R/r marker light missing.
Wellington City Transport Ltd	9-May-13	Fail	Green 2	L/h & R/h outer headlight lens cracked. Washers to operate. L/h rear reflector missing. Notes: Anti graffiti film to be trimmed to 10 mm
Cityline (NZ) Ltd	16-May-13	Fail	Q Pink	Rear floor hatch covering damaged. Rear exit doors sticking.
Cityline (NZ) Ltd	16-May-13	Fail	Q Pink	Front left courtesy glass too close to pole. L/r grab pole loose. Rear floor hatch screw missing allowing exhaust fumes to enter. 4th rear
Cityline (NZ) Ltd	16-May-13	Fail	Green 2	R/h washer to operate. L/h Emergency Exit anti graffiti film to be trimmed 10mm from hammer perimeter. L/h headlight reflector corrosion.
North City Bus Ltd	16-May-13	Fail	Q Pink	L8 aisle seat frame bare metal exposed. R/r Emergency Exit alarm to operate. L9 seat frame loose (floor mount on outer wheel arch).
North City Bus Ltd	16-May-13	Fail	Q Pink	School Bus signs to comply. Engine oil leaks.
North City Bus Ltd	16-May-13	Fail	Green 2	Head lights low beam to operate.
North City Bus Ltd	16-May-13	Fail	Q Pink	R/h washer to operate. Pod mount (behind driver) to be secured. R8 seat to be secured. R/r Emergency Exit anti graffiti film to be trimmed
North City Bus Ltd	16-May-13	Fail	No Action	Not inspected but noted: Oil leak.
North City Bus Ltd	16-May-13	Fail	No Action	Not inspected but noted: Oil leak.
Cityline (NZ) Ltd	31-May-13	Fail	Green 2	R/h headlight reflector corrosion. R3 outer seat loose. Rear seat frame broken.
Cityline (NZ) Ltd	31-May-13	Fail	Green 2	R/h headlight lens cracked. R9 seat loose.
Cityline (NZ) Ltd	31-May-13	Fail	Green 2	R/h headlight reflector discolouration. Note: Seal interior rear pod to prevent exhaust fumes entering. Minor indication of fumes.
Cityline (NZ) Ltd	31-May-13	Fail	Green 2	R/h & L/h headlight reflectors corroded. Note: Seal interior rear pod to prevent exhaust fumes entering. Minor indication of fumes.
Cityline (NZ) Ltd	31-May-13	Fail	Green 2	R9, L9 seats loose. Left rear stanchion pole loose. Notes: Indicator lenses to be cleaned. Cab marker lights to comply. Presently 1 x yellow,
Cityline (NZ) Ltd	31-May-13	Fail	Green 2	R3, R4 seats loose. Rear seat frame broken. Note: R/h headlight reflector discolouration.
Cityline (NZ) Ltd	31-May-13	Pass	No Action	Notes: Fan belt adjusting bolt loose. Seal interior rear pod to prevent exhaust fumes entering. Minor indication of fumes.
Cityline (NZ) Ltd	31-May-13	Fail	Green 2	R/h headlight reflector corrosion. Rear light lenses to be cleaned and/or replaced as required. Note: Minor engine oil leak.
Cityline (NZ) Ltd	31-May-13	Fail	Green 2	R/h outer headlight lens cracked. Left rear stanchion pole loose. Note: Right luggage rack loose.

Operator name	date	result	Inspection	Action	Fault description
Cityline (NZ) Ltd	31-May-13	Fail	Green 2		R/h headlight reflector corrosion. Number plate light missing. R/h 1st stanchion pole loose.
Cityline (NZ) Ltd	31-May-13	Fail	Green 2		R/h & L/h headlight reflectors corroded. R2 seat loose. L/h indicators to operate.
Cityline (NZ) Ltd	31-May-13	Fail	Green 2		Pod behind driver loose. L/h 1st stanchion loose. R8 seat loose. Rear seat squab insecure.
Cityline (NZ) Ltd	31-May-13	Fail	Green 2		R/h headlight reflector corrosion. Notes: Incorrect TSL label displayed. Minor oil leak.
Cityline (NZ) Ltd	31-May-13	Fail	Green 2		R/h Emergency Exit anti graffiti film to be trimmed 10mm from perimeter of window. L/h rear stanchion pole loose.
Cityline (NZ) Ltd	31-May-13	Fail	Green 2		Rear seat insecure. L/h rear stanchion pole loose.
Cityline (NZ) Ltd	31-May-13	Fail	Green 2		R/h headlight corrosion. Cab marker light to operate. Rear seat r/h outer loose.
Cityline (NZ) Ltd	31-May-13	Fail	Green 2		Left rear stanchion pole loose.
Cityline (NZ) Ltd	31-May-13	Fail	Green 2		R3 seat loose. Exhaust leaks into passenger compartment.
Wellington City Transport Ltd	25-Jun-13	Fail	No Action		R/h 2nd Emergency Exit anti graffiti film to be trimmed 10mm from window perimeter. Exterior advertising to be trimmed on emergency
Wellington City Transport Ltd	25-Jun-13	Fail	No Action		R/h 2nd Emergency Exit anti graffiti film to be trimmed 10mm from window perimeter. Rear door courtesy glass mount detached.
Wellington City Transport Ltd	25-Jun-13	Fail	No Action		R/h rear Emergency Exit anti graffiti film to be trimmed 10mm from window perimeter. Note: L3 seat base bolt loose. Note: Rear tag on/
Wellington City Transport Ltd	25-Jun-13	Fail	No Action		L/r door courtesy glass panel to secure. Rear advertising to be trimmed 10 mm around window hammer.
Wellington City Transport Ltd	25-Jun-13	Fail	No Action		TSL label to display. L6, L9 seats to secure.
Wellington City Transport Ltd	25-Jun-13	Fail	No Action		Rear left body damage. Rear exit lower courtesy panel to secure.
Cityline (NZ) Ltd	25-Jun-13	Fail	No Action		R2, R7, L8, L10 seats loose. R3 outer seat mount broken. Engine oil leak.
Cityline (NZ) Ltd	25-Jun-13	Fail	No Action		Cab marker lights different colours. L10 outer seat headrest damaged. Left 1st stanchion to secure. R3 seat base mount loose.
Cityline (NZ) Ltd	25-Jun-13	Fail	No Action		L2, L4, R2 loose bolts to secure. L5 seat squab to secure.
Cityline (NZ) Ltd	25-Jun-13	Fail	No Action		Oil leak from bell housing. Emergency Exit signage r/h rear exterior to replace.
Cityline (NZ) Ltd	25-Jun-13	Fail	No Action		R/h outer headlight lens cracked. Emergency Exit signage to comply (less than 75mm). Engine oil leak.
Cityline (NZ) Ltd	25-Jun-13	Fail	No Action		L3, L10, R7 seats loose. Floor engine hatch bolt to be replaced. R/r Emergency Exit sign to comply.
Cityline (NZ) Ltd	25-Jun-13	Fail	No Action		R7 seat squab to secure. Pod behind driver to secure. Front roof hatch Emergency signage required. Engine oil leaks.
Cityline (NZ) Ltd	25-Jun-13	Fail	No Action		Pod behind driver to secure. L2, L7, L9, R5 seats loose. R7, L/h rear seats squabs to secure. Courtesy glass to adjust. Broken gauge
Cityline (NZ) Ltd	25-Jun-13	Fail	No Action		Engine cover hatch (adjacent to rear door) bolt to be replaced. L/h handrail to secure (beside courtesy glass). Battery cables to secure.
Cityline (NZ) Ltd	25-Jun-13	Fail	No Action		Pod behind driver to secure. R6 wall mount loose. L6, L11, R7, R10, R11, R13 seat mounts loose. L7 seat mount broken. R10 squab
Wellington City Transport Ltd	28-Aug-13	Pass	No Action		
Wellington City Transport Ltd	28-Aug-13	Fail	Pink		Oil leak. L/r tyre tread below minimum.
Wellington City Transport Ltd	28-Aug-13	Fail	Pink		Oil leak / build up left side of motor. Combustible build up on top of fuel tank.
Wellington City Transport Ltd	28-Aug-13	Fail	Pink		Diesel leak pump area. R5 sharp object on stanchion. R6 chin pad to secure, stanchion base to secure. Note: Rear window to secure.
Wellington City Transport Ltd	28-Aug-13	Pass	No Action		
Wellington City Transport Ltd	28-Aug-13	Fail	Green 2		Minor oil leak turbo l/h side. L6, R7 chin pads missing.
Wellington City Transport Ltd	28-Aug-13	Pass	No Action		
Wellington City Transport Ltd	28-Aug-13	Fail	Q Green		Incorrect front door closing pressure.
Wellington City Transport Ltd	28-Aug-13	Fail	Pink		Oil leak l/h side of engine.
Wellington City Transport Ltd	28-Aug-13	Fail	Pink		Oil leak filter area.
Wellington City Transport Ltd	28-Aug-13	Fail	Pink		Engine oil leak - soaking into insulation.
Wellington City Transport Ltd	28-Aug-13	Fail	Pink		Injector fuel leak. Number plate light to operate. L8 seat loose. Combustible build up on fuel tank.
Wellington City Transport Ltd	28-Aug-13	Fail	Pink		Engine & transmission oil leaks. Injector return pipe leaking.
Wellington City Transport Ltd	28-Aug-13	Fail	Pink		Oil leak around turbo.
Wellington City Transport Ltd	28-Aug-13	Fail	Pink		Engine oil leak. Battery insecure (clamp missing).
Wellington City Transport Ltd	28-Aug-13	Fail	Green 2		Incorrect front door closing pressure (ADL to check pressures)
Wellington City Transport Ltd	28-Aug-13	Fail	Green 2		Windscreen washers to operate.
Wellington City Transport Ltd	28-Aug-13	Fail	Green 2		Windscreen washer hose broken. Wiper rubber torn. Note: Engine oil leak.
Wellington City Transport Ltd	28-Aug-13	Pass	No Action		
Wellington City Transport Ltd	28-Aug-13	Pass	No Action		
Wellington City Transport Ltd	28-Aug-13	Pass	No Action		
Wellington City Transport Ltd	28-Aug-13	Pass	No Action		
Wellington City Transport Ltd	28-Aug-13	Pass	No Action		
Wellington City Transport Ltd	28-Aug-13	Fail	Pink		Engine oil leak.
Wellington City Transport Ltd	28-Aug-13	Fail	Pink		Engine oil leak - r/h side timing cover.
Wellington City Transport Ltd	28-Aug-13	Fail	Pink		Engine oil leaks - r/h side & compressor. Note: Door closing guides bolts loose.
Wellington City Transport Ltd	28-Aug-13	Fail	Green 2		Hydraulic oil leak - rectified & cleaned on site.
Wellington City Transport Ltd	28-Aug-13	Fail	Green 2		Number plate light to operate. Minor oil leak (gasket).
Wellington City Transport Ltd	28-Aug-13	Fail	Green 2		Oil residue around oil filter.
Wellington City Transport Ltd	28-Aug-13	Pass	No Action		Note: Steam clean diesel tank.
Cityline (NZ) Ltd	28-Aug-13	Fail	Green 2		Oil leak around oil filter seal.
Cityline (NZ) Ltd	28-Aug-13	Pass	No Action		Notes: Rear Emergency Exit door alarm intermittent. Minor power steering oil leak. Exhaust pipe to be extended beyond bodywork.
Cityline (NZ) Ltd	28-Aug-13	Pass	No Action		Note: L/h headlight reflector corrosion.
Cityline (NZ) Ltd	28-Aug-13	Pass	No Action		

Operator name	date	result	Inspection	Action	Fault description
Cityline (NZ) Ltd	28-Aug-13	Pass	No Action		Note: Accumulated dirt around fuel tank - steam clean.
Cityline (NZ) Ltd	28-Aug-13	Pass	No Action		Note: To confirm rear window is Toughened glass (Confirmed Andrew 28/8/2013). Exhaust pipe to be extended beyond bodywork.
Cityline (NZ) Ltd	28-Aug-13	Pass	No Action		
Cityline (NZ) Ltd	28-Aug-13	Pass	No Action		
Cityline (NZ) Ltd	28-Aug-13	Fail	Green		Exhaust system leak (before muffler).
Cityline (NZ) Ltd	28-Aug-13	Pass	No Action		
Cityline (NZ) Ltd	28-Aug-13	Pass	No Action		
Cityline (NZ) Ltd	28-Aug-13	Fail	Green 2		L/h headlight high beam to operate. Note: Interior generally untidy.
Cityline (NZ) Ltd	28-Aug-13	Fail	Green 2		Fuel cap leaking (minor). Steam clean diesel tank.
Cityline (NZ) Ltd	28-Aug-13	Pass	No Action		Note: L/r aisle floor hatch trip hazard.
Cityline (NZ) Ltd	28-Aug-13	Pass	No Action		
Cityline (NZ) Ltd	28-Aug-13	Fail	Pink		Brake lights to operate. Fuel injector #1 leaking. Injector pipe on pump leaking. Oil leak (minor) at dipstick tube.
Cityline (NZ) Ltd	28-Aug-13	Pass	No Action		
Cityline (NZ) Ltd	28-Aug-13	Pass	No Action		
Cityline (NZ) Ltd	28-Aug-13	Pass	No Action		Note: Steam clean engine.
Cityline (NZ) Ltd	28-Aug-13	Pass	No Action		Notes: Small hose in cooling system to be replaced. Engine inspection cover - seal missing.
Cityline (NZ) Ltd	28-Aug-13	Fail	Pink		Diesel fuel leak (fuel meter guage).
Cityline (NZ) Ltd	28-Aug-13	Pass	No Action		Note: Steam clean fuel tank.
Cityline (NZ) Ltd	28-Aug-13	Pass	No Action		
Cityline (NZ) Ltd	28-Aug-13	Pass	No Action		External inspection only - nil faults.
Cityline (NZ) Ltd	28-Aug-13	Fail	Pink		Engine oil leak.
Cityline (NZ) Ltd	28-Aug-13	Fail	Pink		Engine oil leak.
Cityline (NZ) Ltd	28-Aug-13	Pass	No Action		Note: Steam clean fuel tank.
Cityline (NZ) Ltd	28-Aug-13	Fail	Pink		Engine oil leak. Possible exhaust leaks into passenger compartment (indication on rear interior panel).
North City Bus Ltd	28-Aug-13	Fail	Green 2		Oil accumulation in engine compartment.
North City Bus Ltd	28-Aug-13	Fail	Green 2		Insecure battery.
North City Bus Ltd	28-Aug-13	Fail	Pink		Oil leak onto exhaust. R/h lower rear light to operate. Number plate light to operate. Battery insecure.
North City Bus Ltd	28-Aug-13	Pass	No Action		Notes: Steam clean fuel tank. R3 stanchion loose.
Wellington City Transport Ltd	29-Aug-13	Fail	Green 2		L6, R7 chin pads missing. L/h headlight to operate.
North City Bus Ltd	29-Aug-13	Pass	No Action		Notes: Material (possibly flammable) near starter motor. L/r courtesy glass to be adjusted.
North City Bus Ltd	29-Aug-13	Fail	Green		Rear Emergency Exit door alarm to operate. (Completed 29/8/13 - Andrew)
North City Bus Ltd	29-Aug-13	Fail	Green 2		Rear Emergency Exit door alarm to operate - intermittent. (Completed 29/8/13 - Andrew)
North City Bus Ltd	29-Aug-13	Fail	Green		Rear Emergency Exit door alarm to operate - intermittent. (Completed 29/8/13 - Andrew). R/r body panel to be repaired. L/h rear
North City Bus Ltd	29-Aug-13	Pass	No Action		Note: Minor oil leak at bell housing.
North City Bus Ltd	29-Aug-13	Fail	Pink		Diesel fuel leaking onto exhaust manifold. Rear exterior emergency signage to comply.
North City Bus Ltd	29-Aug-13	Pass	No Action		
North City Bus Ltd	29-Aug-13	Pass	No Action		
Cityline (NZ) Ltd	29-Aug-13	Pass	No Action		
Cityline (NZ) Ltd	29-Aug-13	Pass	No Action		
Cityline (NZ) Ltd	29-Aug-13	Fail	Pink		Oil leaking. Oil residue build up near exhaust. L6, R7 chin pads missing. Note: Rear window water leakage.
Cityline (NZ) Ltd	29-Aug-13	Fail	Pink		Driver's seat insecure. Emergency Exit signage instructions missing. L6, R7 chin pads missing. Note: Rear window water leakage.
Cityline (NZ) Ltd	29-Aug-13	Fail	Green 2		L6, R7 chin pads missing. Minor diesel leak & accumulation. Alternator bracket broken. Coolant leakage.
Cityline (NZ) Ltd	29-Aug-13	Pass	No Action		Note: Steam clean engine bay.
Cityline (NZ) Ltd	29-Aug-13	Pass	No Action		Note: Replace mirror above rear door.
Cityline (NZ) Ltd	29-Aug-13	Fail	Pink		Battery box to secure. Engine oil leak. Coolant leakage. Emergency Exit instructions missing. Brake pedal rubber to be replaced.
Cityline (NZ) Ltd	29-Aug-13	Fail	Green		Rear bench seat brackets exposed. Floor hatch securing bolt missing.
Cityline (NZ) Ltd	29-Aug-13	Fail	Pink		Oil accumulation on engine & fuel tank.
Cityline (NZ) Ltd	29-Aug-13	Fail	Pink		Leak & oil accumulation at hydraulic tank. Front of engine oil leak. Oil leak timing cover seal. Oil accumulation fuel tank.
Cityline (NZ) Ltd	29-Aug-13	Fail	Green 2		Windscreen washers to operate. Route destination indicator loose. Notes: Minor oil leak at dipstick tube. Steam clean around Non slip floor covering worn in aisle.hydraulic pump.
Cityline (NZ) Ltd	29-Aug-13	Fail	Pink		Combustible build up on engine, fuel tank, hydraulic tank, hydraulic fan. Note: Anti freeze dripping to ground.
Cityline (NZ) Ltd	29-Aug-13	Fail	Pink		Engine oil leak. Combustible build up on fuel tank.
Cityline (NZ) Ltd	29-Aug-13	Pass	No Action		Note: Steam clean fuel tank.
Cityline (NZ) Ltd	29-Aug-13	Pass	No Action		
Cityline (NZ) Ltd	29-Aug-13	Pass	No Action		Note: Possible exhaust fumes entering at back panel corners.
Cityline (NZ) Ltd	29-Aug-13	Pass	No Action		Note: R/r tyre cracks on sidewall.
Cityline (NZ) Ltd	29-Aug-13	Fail	Pink		Engine oil leak.
Cityline (NZ) Ltd	29-Aug-13	Pass	No Action		
Cityline (NZ) Ltd	29-Aug-13	Pass	No Action		
Cityline (NZ) Ltd	29-Aug-13	Pass	No Action		

Operator name	date	result	Action	Fault description
Cityline (NZ) Ltd	29-Aug-13	Pass	No Action	Note: Steam clean fuel tank.
Cityline (NZ) Ltd	29-Aug-13	Pass	No Action	Note: Rear seat mount broken.
Cityline (NZ) Ltd	29-Aug-13	Pass	No Action	
Cityline (NZ) Ltd	29-Aug-13	Pass	No Action	Note: Steam clean fuel tank.

RELEASED UNDER THE
OFFICIAL INFORMATION ACT