



А

evision

55 Rata Road


GIS-3320901-51





124-154 Te Moana Road

Status:		
Document ID:	Rev.	
Drawing No:	A	
GIS-3320901-55		



Date

Sector 2: 55 Rata Road

Status:		
Document ID:	Rev.	
Drawing No:		
GIS-3320901-61	A	







## Environmental Test Pit



Non Natural Materials Encountered

## **Proposed Alignment**

All exceedances are above environmental risk criteria unless noted otherwise

This map contains data derived in part or wholly from sources other than Beca, and therefore, no representations or warranties are made by Beca as to the accuracy or completeness of this information.

> Map intended for distribution as a PDF document. Scale may be incorrect when printed.

Contains Crown Copyright Data. Crown Copyright Reserved.




0	20	40		80
		Metres		
	Scale	1:1,500	at A3	

## MACKAYS TO PEKA PEKA EXPRESSWAY


Contaminants Exceeding Guideline Values Sector 2: Kāpiti Road Intersection

Status:		
Document ID:	Rev.	
Drawing No:	Δ	
GIS-3320901-62	A	



Status:		
Document ID:	Rev.	
Drawing No:	А	
GIS-3320901-63		





Author: HEC. Drawing Plotted: Wednesday, 7 March 2012

