


# State Highway 3

## Ohaupo to Te Awamutu Safety Improvements




### Where wire rope barriers are working

Wire rope median barriers are proven to reduce run-off-road and head-on crashes. They've been installed in a number of locations around the country with very positive results.




#### SH1 Centennial Highway - Kapiti Coast

Barrier installed 2005/2006



#### SH58 Haywards - Greater Wellington

Barrier installed 2003



#### SH1 Rangiriri - Waikato

Barrier installed 2005

