

SAFETY ALERT

Redundant TTM Equipment URGENT ACTION REQUIRED

The presence of redundant TTM equipment on the Auckland Transport road corridor is a significant issue.

AT must now take action in the form of non-conformance issuance and associated recovery of costs.

AT have advised in prior communications of this issue but have unfortunately seen the problem grow. We have had members of the community injured and continue to lose compliance from drivers (particularly when TSLs are left in place).

Please take immediate and ongoing action to remove your equipment from sites.

If you have any queries or suggestions relating to this matter, please feel free to contact myself or any of the team.

For further information please contact

Al Christ

Road Corridor Access Manager

al.christ@at.govt.nz